



Angle Drill

彎頭電鑽


حفر بزاوية

D 10YB

Handling instructions

使用說明書

تعليمات المعالجة




Read through carefully and understand these instructions before use.


使用前務請詳加閱讀。

اقرأ التعليمات التالية بعناية قبل الاستخدام.


1




2




3




4



5



6



	English	中國語	العربية
①	Reversing switch lever	換向開關柄	قلب ذراع المفتاح
②	Drill chuck	鑽子卡盤	مقبض الحفر
③	Chuck wrench	卡盤扳手	مفتاح الظرف
④	Switch lever	開關柄	ذراع المفتاح
⑤	Switch on	開關打開	تشغيل
⑥	Round convex on surface of switch lever	開關柄表面球形凸起	محدب مستدير على سطح ذراع المفتاح
⑦	Switch off	開關關閉	إيقاف تشغيل
⑧	Dial	撥盤	قرص مدرج
⑨	Wear limit	磨損極限	حد التأكل
⑩	No. of Carbon Brush	碳刷號	عدد الفرش الكربونية

GENERAL SAFETY RULES

WARNING!

Read all instructions

Failure to follow all instructions listed below may result in electric shock, fire and/or serious injury.

The term "power tool" in all of the warnings listed below refers to your mains-operated (corded) power tool or battery-operated (cordless) power tool.

SAVE THESE INSTRUCTIONS

1) Work area

a) Keep work area clean and well lit.

Cluttered and dark areas invite accidents.

b) Do not operate power tools in explosive atmospheres, such as in the presence of flammable liquids, gases or dust.

Power tools create sparks which may ignite the dust of fumes.

c) Keep children and bystanders away while operating a power tool.

Distractions can cause you to lose control.

2) Electrical safety

a) Power tool plugs must match the outlet.

Never modify the plug in any way.

Do not use any adapter plugs with earthed (grounded) power tools.

Unmodified plugs and matching outlets will reduce risk of electric shock.

b) Avoid body contact with earthed or grounded surfaces such as pipes, radiators, ranges and refrigerators.

There is an increased risk of electric shock if your body is earthed or grounded.

c) Do not expose power tools to rain or wet conditions.

Water entering a power tool will increase the risk of electric shock.

d) Do not abuse the cord. Never use the cord for carrying, pulling or unplugging the power tool.

Keep cord away from heat, oil, sharp edges or moving parts.

Damaged or entangled cords increase the risk of electric shock.

e) When operating a power tool outdoors, use an extension cord suitable for outdoor use.

Use of a cord suitable for outdoor use reduces the risk of electric shock.

3) Personal safety

a) Stay alert, watch what you are doing and use common sense when operating a power tool.

Do not use a power tool while you are tired or under the influence of drugs, alcohol or medication.

A moment of inattention while operating power tools may result in serious personal injury.

b) Use safety equipment. Always wear eye protection.

Safety equipment such as dust mask, non-skid safety shoes, hard hat, or hearing protection used for appropriate conditions will reduce personal injuries.

c) Avoid accidental starting. Ensure the switch is in the off position before plugging in.

Carrying power tools with your finger on the switch or plugging in power tools that have the switch on invites accidents.

d) Remove any adjusting key or wrench before turning the power tool on.

A wrench or a key left attached to a rotating part of the power tool may result in personal injury.

e) Do not overreach. Keep proper footing and balance at all times.

This enables better control of the power tool in unexpected situations.

f) Dress properly. Do not wear loose clothing or jewellery. Keep your hair, clothing and gloves away from moving parts.

Loose clothes, jewellery or long hair can be caught in moving parts.

g) If devices are provided for the connection of dust extraction and collection facilities, ensure these are connected and properly used.

Use of these devices can reduce dust related hazards.

4) Power tool use and care

a) Do not force the power tool. Use the correct power tool for your application.

The correct power tool will do the job better and safer at the rate for which it was designed.

b) Do not use the power tool if the switch does not turn it on and off.

Any power tool that cannot be controlled with the switch is dangerous and must be repaired.

c) Disconnect the plug from the power source before making any adjustments, changing accessories, or storing power tools.

Such preventive safety measures reduce the risk of starting the power tool accidentally.

d) Store idle power tools out of the reach of children and do not allow persons unfamiliar with the power tool or these instructions to operate the power tool.

Power tools are dangerous in the hands of untrained users.

e) Maintain power tools. Check for misalignment or binding of moving parts, breakage of parts and any other condition that may affect the power tools' operation.

If damaged, have the power tool repaired before use.

Many accidents are caused by poorly maintained power tools.

f) Keep cutting tools sharp and clean.

Properly maintained cutting tools with sharp cutting edges are less likely to bind and are easier to control.

g) Use the power tool, accessories and tool bits etc., in accordance with these instructions and in the manner intended for the particular type of power tool, taking into account the working conditions and the work to be performed.

Use of the power tool for operations different from intended could result in a hazardous situation.

5) Service

a) Have your power tool serviced by a qualified repair person using only identical replacement parts.

This will ensure that the safety of the power tool is maintained.

PRECAUTION

Keep children and infirm persons away.

When not in use, tools should be stored out of reach of children and infirm persons.

PRECAUTIONS ON USING ANGLE DRILL

1. Hold the drill and side handle securely with both hands when using.
2. Do not wear gloves made of stuff liable to roll up such as cotton, wool, cloth or string, etc.
3. Prior to drilling into walls, ceilings or floors, ensure there are no electric cables or conduits inside.

SPECIFICATIONS

Voltage (by areas)*	(110 V, 115 V, 220 V, 230 V, 240 V) ~
Power input*	500 W
No-load speed	500 – 2300 /min
Drill chuck capacity	10 mm
Capacity: Steel	10 mm
Wood	22 mm
Weight (without cord)	1.5 kg

* Be sure to check the nameplate on product as it is subject to change by areas.

STANDARD ACCESSORIES

- (1) Chuck wrench 1
 (2) Side handle 1

Standard accessories are subject to change without notice.

APPLICATIONS

- Drilling holes on various metal, wood and plastics.

PRIOR TO OPERATION

1. Power source

Ensure that the power source to be utilized conforms to the power requirements specified on the product nameplate.

2. Power switch

Ensure that the power switch is in the OFF position. If the plug is connected to a receptacle while the power switch is in the ON position, the power tool will start operating immediately, inviting serious accident.

3. Extension cord

When the work area is removed from the power source, use an extension cord of sufficient thickness and rated capacity. The extension cord should be kept as short as practicable.

4. Confirm the direction of bit rotation (Fig. 1)

The bit rotates clockwise (viewed from the top side) by pushing the R-side of the reversing switch lever. The L-side of the lever is pushed to turn the bit counterclockwise.

CAUTION

Never change the direction of bit rotation while operating.

Turn the power switch OFF before changing the direction of bit rotation; otherwise, burning of the motor will result.

5. Mounting drill bits (Fig. 2)

Tighten drill bits with the chuck wrench. There are three holes in which the chuck wrench should be inserted. Tighten them equally in turn at three holes, without tightening them only at one hole. The drill bit can be removed in the opposite method as mentioned above.

6. How to select drill bits

- (1) When drilling holes in metals or plastics:
Use ordinary metalworking drill bits, applicable drill sizes range from min. 1.5 mm to drill chuck capacity.
- (2) When drilling holes in wood:
Use woodworking drill bits. For small holes of 6.5 mm diam. or below, use metalworking drill bits.

7. Fixing the side handle

Screw the side handle into the gear cover.

HOW TO USE

1. Switching instruction

- (1) Turning the switch on
Slide the switch lever on the main body backward as illustrated in Fig. 3. When you slide it backward completely, the switch gets turned on and locked in that condition.

- (2) Turning the switch off

Press the round convex on the surface of the switch lever as illustrated in Fig. 4. Then, the lock comes off, the switch lever returns forward on the main body by the spring's force, and the switch gets turned off.

CAUTION

Check and make sure positively that the switch is off before inserting the plug into the power outlet. Otherwise, a sudden start of the tool definitely results in an accident.

2. Pressing force of drill

You can not get holes quickly even if pressing it by strong force more than necessary.

It not only damages the tip of drill bits and decreases the efficiency of operation, but also shortens the life of the drill.

3. When drilling completely through the material

When the drill bit bores completely through the material, careless handling often results in a broken drill bit or damage to the drill body itself due to the sudden movement of the drill. Always be alert and ready to release pushing force and hold the drill body securely with both hands when drilling through the material.

4. Adjusting the drilling speed

D10YB is equipped with electric control circuit which enables non-step speed control.

To adjust the speed, turn the dial shown in **Fig. 5**. When the dial is set to "1", the drilling speed is minimum speed (500 /min). When the dial is set to "5", the drilling speed is maximum speed (2300 /min). Adjust the drilling speed according to the material.

NOTE

When the dial is set to "1", there can be cases where no rotation takes place due to a power situation, etc. In this case, raise the dial slightly before use.

MAINTENANCE AND INSPECTION

1. Inspecting the drill bits

Since use of an abraded drill bits will cause motor malfunctioning and degraded efficiency, replace the drill bits with a new one or resharpening without delay when abrasion is noted.

2. Inspecting the mounting screws:

Regularly inspect all mounting screws and ensure that they are properly tightened. Should any of the screws be loose, retighten them immediately. Failure to do so could result in serious hazard.

3. Maintenance of the motor

The motor unit winding is the very "heart" of the power tool. Exercise due care to ensure the winding does not become damaged and/or wet with oil or water.

4. Inspecting the carbon brushes (Fig. 7)

The motor employs carbon brushes which are consumable parts. Since an excessively worn carbon brush can result in motor trouble, replace the carbon brushes with new ones which have the same carbon brush No. shown in the figure when they become worn to or near the "wear limit". In addition, always keep carbon brushes clean and ensure that they slide freely within the brush holders.

5. Replacing carbon brushes

Disassemble the brush caps with a slotted-head screwdriver the carbon brushes can be easily removed.

NOTE

Due to HIKOKI's continuing program of research and development, the specifications herein are subject to change without prior notice.

一般安全規則

警告！

閱讀所有說明

未遵守下列之說明可能導致電擊、火災及/或嚴重傷害。

「電動工具」一詞在下列警告中，關係到電源操作（有線）之電動工具或電池操作（無線）之電動工具。

記住這些說明

1) 工作場所

a) 保持工作場所清潔及明亮。

雜亂及昏暗區域易發生意外。

b) 勿在易產生爆炸之環境中操作，譬如有易燃液體、瓦斯或粉塵存在之處。

電動工具產生火花會引燃粉塵或煙氣。

c) 當操作電動工具時，保持兒童及過往人員遠離。

分神會讓你失去控制。

2) 電氣安全

a) 電動工具插頭必須與插座配合，絕不可以任何方法修改插頭，且不得使用任何轉接插頭於有接地之電動工具。

不修改插頭及所結合之插座可減少電擊。

b) 避免身體接觸到接地面諸如管子、散熱器、爐灶及冰箱。

如果你的身體接地或搭地，會增加電擊的危險。

c) 勿讓電動工具淋雨或曝露在潮濕的環境下。

電動工具進水會增加電繫的危險。

d) 勿濫用電源線。絕勿使用電源線去纏繞、拖拉電動工具或拔插頭，保持電源線遠離熱氣、油氣、尖角或可動零件。

損壞或纏繞的電源線會增加電繫之危險。

e) 電動工具在室外操作時要使用一適合室外用的延長線。

使用合適之室外用延長線會減少電擊的危險。

3) 人員安全

a) 保持機警，注意你正在做什麼，並運用普通常識操作電動工具。

當你感到疲勞或受藥品、酒精或醫療影響時，勿操作電動工具。

操作中瞬間的不注意可能造成人員嚴重的傷害。

b) 使用安全裝備，常時佩戴安全眼鏡。

安全裝備有防塵口罩、防滑安全鞋、硬帽，或在適當情況下使用聽覺防護，可減少人員傷害。

c) 避免意外地啟動。在插電前確認開關是在“off”的位置。

以手指放在開關握持電動工具，或在電動工具的開關於“on”的狀況下插上插頭，都會導致意外發生。

d) 在將電動工具啟動前，先卸下任何調整用鑰匙或扳手。

扳手或鑰匙遺留在電動工具的轉動部位時，可能導致人員傷害。

e) 身體勿過度伸張，任何時間要保持站穩及平衡。

以便在不預期的狀態下，能對電動工具有較好的控制。

f) 衣著要合宜，別穿太鬆的衣服或戴首飾。

保持你的頭髮、衣服及手套遠離轉動部位。寬鬆的衣服、首飾及長髮會被捲入轉動部位。

g) 如果裝置要用於粉塵抽取及集塵設施，要確保其連接及正當使用。

使用此類裝置能減少與粉塵有關之危害。

4) 電動工具之使用及注意事項

a) 勿強力使用電動工具，使用正確之電動工具為你所需。

正確使用電動工具會依其設計條件使工作做得更好更安全。

b) 如果開關不能轉至開及關的位置，勿使用電動工具。

任何電動工具不能被開關所控制是危險的，必須要修理。

c) 在做任何調整、更換配件或收存電動工具時，要將插頭與電源分開，且/或將電池從電動工具中取出。

此種預防安全措施可減少意外開啟電動機之危險。

d) 收存停用之電動工具，遠離兒童，且不容許不熟悉電動工具或未瞭解操作電動工具說明書的人操作電動工具。

在未受過訓練的人手裡，電動工具極為危險。

e) 保養電動工具，檢核是否有可動零件錯誤的結合或卡住、零件破裂及可能影響電動工具操作的任何其他情形。

電動工具如果損壞，在使用前要修好。許多意外皆肇因於不良的保養。

f) 保持切割工具銳利清潔。

適當的保養切割工具，保持銳利之切削鋒口，可減少卡住並容易控制。

g) 按照說明書使用電動工具、配件及刀具等，使用特殊型式之電動工具時要考量工作條件及所執行之工作。

使用電動工具未如預期用途之操作時，會導致危害。

5) 維修

- a) 讓你的電動工具由合格修理人員僅使用相同的維修零件更換。

如此可確保電動工具的安全得以維持。

注意事項

不可讓孩童和體弱人士靠近工作場所。

應將不使用的工具存放在孩童和體弱人士伸手不及的地方。

使用彎頭電鑽時的注意事項

1. 使用時用雙手緊緊拿住電鑽和側柄。
2. 請勿戴用易於被卷起的材料（如棉、毛、布或棉線等）織成的手套。
3. 在牆上、天花板或地板上鑽孔之前，請確認其中無電纜或管道通過。

規 格

電壓 (按地區)*	(110 V, 115 V, 220 V, 230 V, 240 V) ~	
輸入功率*	500W (台灣: 470W)	
額定輸出功率	250W	
無負荷速度	500 - 2300轉/分	
電鑽卡盤容量	10 mm	
能 力	金 屬	10 mm
	木 材	22 mm
重量 (不含線纜)	1.5 kg	

* 當須改變地區時應檢查產品上的銘牌。

標 準 附 件

- (1) 卡盤扳手 1
 (2) 側柄 1

標準附件可能不預先通告而徑予更改。

用 途

- 在各種金屬，木材和塑料上鑽孔。

作 業 之 前

1. 電 源

確認所使用的電源與工具銘牌上標示的規格是否相符。

2. 電 源 開 關

確認電源開關是否切斷。若電源開關接通，則插頭插入電源插座時電動工具將出其不意地立刻轉動，從而招致嚴重事故。

3. 延伸線纜

若作業場所移到離開電源的地點，應使用容量足夠，鑽裝合適的延伸線纜，並且要盡可能地短些。

4. 確認鑽頭轉向 (圖 1)

按下反向開關柄的 R - 側時，鑽頭便按順時針方向旋轉。而按下開關柄的 L - 側時，鑽頭則按逆時針方向旋轉。

注意：切勿在操作時更改鑽頭的轉向。

更改鑽頭的轉向前，請關掉電源開關。否則，會燒毀馬達。

5. 安裝鑽頭

用夾頭扳手擰緊鑽頭。在夾頭上有三個夾頭扳手可以插入的孔，平均用力擰三個孔固定鑽頭，不要只擰一個孔固定鑽頭。用上述的相反動作即可拆下鑽頭。

6. 怎樣選擇鑽頭

(1) 在金屬或塑料上鑽孔時

用普通金屬加工鑽頭，可用的鑽頭大小：從最小 1.5 mm 到最大能力。

(2) 在木材上鑽孔時

用普通木材加工鑽頭。鑽等子或小於 6.5 mm 的小孔徑時用金屬加工鑽頭。

7. 固定側柄

把側柄旋進齒輪罩。

彎頭電鑽的使用方法

1. 轉換說明

(1) 打開開關

如圖 3 所示，向後撥動鑽體上的開關柄。將其向後完全轉動時，開關便會打開並被鎖定於該狀態。

(2) 關閉開關

如圖 4 所示，按開關柄表面的圓形凸起後鎖定被取消，開關柄靠彈簧壓力回到鑽體前部，並且開關被關閉。

注意：在將插頭插入電源插座之前，務請確認開關處於關閉狀態。否則，電動工具突然起動會導致事故發生。

2. 彎頭電鑽的壓力

不可用超過正常的壓力來加快鑽孔速度。這樣不僅會損壞鑽頭尖，降低工作效率，而且會縮短電鑽壽命。

3. 鑽通材料時

當鑽頭完全鑽通材料時，請小心操作，否則電鑽的突然移動會導致鑽頭或電鑽受損。當將要鑽通材料時，請時刻警惕，作好釋放壓力的準備，並用雙手抓緊電鑽。

4. 調整鑽孔速度

D10YB 帶有電子控制電路，可進行無級速度控制。

要調整速度時，轉動圖 5 所示的撥盤。當撥盤設定於“1”時，鑽孔速度為最慢速度（500 轉/分）；當撥盤設定於“5”時，鑽孔速度為最快速度（2300 轉/分）。請根據材料調整鑽孔速度。

注意：撥盤的刻度為“1”時，有時因電源等原因而不轉動。這時，請提高撥盤的刻度後再使用。

維護和檢查

1. 檢查鑽頭

由於使用磨損後的鑽頭會使馬達工作失常，並會降低效率。所以一旦發現鑽頭磨損，應立即用新的鑽頭或者磨鋒利的鑽頭進行更換。

2. 檢查安裝螺釘

要經常檢查安裝螺釘是否緊固妥善。若發現螺釘鬆了，應立即重新扭緊，否則會導致嚴重的事故。

3. 電動機的維護

電動機繞線是電動工具的心臟部。應仔細檢查有無損傷，是否被油液或水沾濕。

4. 檢查碳刷（圖 7）

馬達使用碳刷，它是消耗部品，因為使用過久的碳刷將會導致馬達故障，用具有相同碳刷號的新碳刷去更換舊的，碳刷編號用數字表示碳刷何時用舊或接近於磨損極限此外，要經常保持碳刷清潔以及保証它在刷握裡能自由滑動。

5. 更換碳刷

用無頭螺絲刀卸下碳刷蓋，然後可以很容易地取下碳刷。

注意：為求改進，本手冊所載規格可能不預先通告而徑予更改。

4 ضبط سرعة المتفق

تم تجهيز D10YB بـ“داتة تحكم كهربية والتي تمكن التحكم ذات السرعة غير التدريجية.

لضبط السرعة، قم بتنويم القرص الموضح في الشكل 5 عند ضبط القرص على "1"، يكون الحد الأدنى لسرعة التقب هو (500 دقيقة). عند ضبط القرص على "5"، يكون الحد الأقصى لسرعة التقب هو (2300 دقيقة). قم بضبط سرعة التقب وفقاً للمادة.

ملاحظة

عندما يتم ضبط القرص على "1"، من الممكن أن تتواجد بعض الحالات التي لا يحيط بها تنويم بسبب وضع الطاقة، وغير ذلك. في هذه الحالة، ارفع القرص برفق قبل الاستخدام.

الصيانة والفحص**1 فحص مثاقب الحفر**

نظرًا إلى أن مثاقب الحفر المتراكمة تؤدي إلى تلف المحرك والتقليل من الكفاءة، استبدل مثاقب الحفر أو قم بتشذيبها فور ملاحظتك لأي تأكل.

2 فحص مسامير التثبيت

قم بالفحص الدوري لـ“كافة مسامير التثبيت والتتأكد من إحكام ربطها بشكل صحيح. في حالة فك أي مسامير، قم بإحكام ربطها على الفور. فقد يعرض الفشل في القيام بذلك إلى مخاطر.

3 صيانة المحرك

ملف وحدة المحرك هو "الجزء الأوسط" من أداة الطاقة. تأكد باستمرار من عدم تلف الملف وأولئك بواسطة الزيت أو الماء.

4 فحص الفرشاة الكربونية (الشكل 7)

يسْتهلك المحرك الفرشاة الكربونية وهي من الأجزاء غير معمرة. نظرًا لأن تأكل الفرشاة الكربونية قد ينبع عن وجود مشاكل بالمحرك، قم باستبدال الفرشاة الكربونية بأخرى جديدة لديها نفس رقم الفرشاة الكربونية كما هو موضح في الشكل عند تناقلها أو اقتراها من "حد التأكل". بالإضافة إلى ذلك، قم بتنظيف الفرشاة الكربونية باستمرار والتتأكد من ازلاقها بسلاسة داخل مقابض الفرشاة.

5 استبدال الفرشاة الكربونية

قم بفك أغطية الفرشاة باستخدام مفك صغير برأس ذو فتحات. وبعد ذلك يمكن نزع الفرش الكربونية بسهولة.

ملاحظة

تبعًا لبرنامج HiKOKI للبحث والتطوير المستمر، تتغير المواصفات المذكورة هنا دون إعلام مسبق.

الاحتياطات اللازمة عند استخدام الحفر بزاوية

- 1 امسك المتنبّع وضع المقبض جانباً يامن بكلتا اليدين عند الاستخدام.
- 2 لا ترتدى قفازات مصنوعة من مادة خام عرضة لأن تلتف حول نفسها مثل القطن أو الصوف أو القماش أو خطأ أو غيرها.
- 3 قبل أن تقوم بعمليات الحفر في الحائط، والأسفلت أو الأرضيات، تأكّد من عدم وجود كابلات كهربائية أو موصلات بالداخل.

المواصفات

الجهد الكهربائي (حسب المناطق)*	110 فولت 115 فولت 220 فولت 230 فولت 240 فولت) ~
إدخال الطاقة*	500 وات
السرعة بدون حمل	ـ 2300 - 500 / دقيقة
سرعة ظرف المتنبّع	ـ 10 مم
السعه: الصلب	ـ 10 مم
الخشب	ـ 22 مم
الوزن (بدون السلك)	ـ 1.5 كجم

* تأكّد من فحص لوحة الاسم الموجودة على المنتج حيث أنها عُرضة للتغيير حسب المنطقة.

6 كيفية تحديد متنبّع الحفر

(1) عند عمل فتحات في المعادن أو المواد البلاستيكية: استخدم متنبّع حفر المواد المعدنية العالية، تزدّوا أحجام المتنبّع المستخدم بحد أدنى 1.5 مم لسلعة مقبض الحفر.

(2) عند عمل فتحات في المواد الخشبية: استخدم متنبّع حفر المواد الخشبية. بالنسبة لفتحات الصغيرة بقطار 6.5 مم، أو أقل، استخدم متنبّع حفر للمواد المعدنية.

7 قم بتنبيّت المقبض الجانبي
قم بتنبيّت المقبض الجانبي بغلاف الترس.

ملحقات قياسية

- 1 مفتاح الظرف.....
- 2 مقبض جانبي.....
- 1 يمكن تغيير الملحقات القياسية دون إخطار.

تطبيقات

○ تقبّل الفتحات على الأسطح المعدنية والخشبية والبلاستيكية المتنوعة.

قبل التشغيل

1 مصدر الطاقة

تأكّد من أن مصدر الطاقة الذي سيتم استخدامه مطابق لمتطلبات الطاقة المحددة على لوحة الاسم الموجودة على المنتج.

2 مفتاح الطاقة

تأكّد من أن مفتاح الطاقة على الوضع إيقاف. في حالة توصيل القابس بالقابس وترك مفتاح الطاقة على الوضع تشغيل، فيتم تشغيل أداة الطاقة على الفور، مما قد يؤدي إلى وقوع حادث خطير.

3 سلك التوصيل الإضافي

عند إزالة منطقة العمل من مصدر الطاقة، استخدم سلك توصيل إضافي ذو سمك كافٍ وسرعة مقتنة. يجب أن يظل سلك التوصيل الإضافي قصيراً بما ي足以ه.

4 تأكّد من اتجاه دوران المتنبّع (الشكل 1)

يدور المتنبّع في اتجاه عقارب الساعة (التي تظهر من الجانب الطليوي) بالضغط على جانب R من زراع مقناع القلب. يتم دفع الجانب L لإدارة اللقمة عكس اتجاه عقارب الساعة.

5 تبيّه

لا تغير اتجاه دوران اللقمة أثناء التشغيل مطلقاً.

قم بـإيقاف تشغيل مفتاح الطاقة قبل تغيير اتجاه دوران اللقمة، وإلا، سينتزع عن ذلك احتراق المحرك.

5 تركيب متنبّع الحفر (الشكل 2)

احكم متنبّع الحفر بمفتاح الطرف فيها. اربطها بالتساوي بلفه في الفتحات الثلاث، دون ربطها في فتحة واحدة فقط. يمكن إزاله اللقمة التقبّب بأسلوب معاكس لما هو وارد أعلاه.

كيفية الاستخدام

1 تعليمات التشغيل

(1) قم بشغيل المفتاح

قم بـتحريك زراع المقناط على الهيكل الرئيسي للخلف كما هو موضح في الشكل 3. عندما تقوم بتحريكه للخلف تماماً، سوف يتم تشغيل المفتاح ويتبع إغلاقه في هذه الحالة.

(2) قم بإيقاف تشغيل المفتاح

اضغط على الحدب المستدير على سطح زراع المقناط كما هو موضح في الشكل 4. بعد ذلك، يتم إيقاف تشغيل القفل، يعود زراع المقناط للأمام على الهيكل الرئيسي من خلال ضغط عمود الدوران، وإيقاف تشغيل المفتاح.

تنبيه

تأكّد من إيقاف تشغيل المفتاح بياحيائه قبل إدخال القابس في مأخذ الطاقة. والا، فقد يتrogen عند التشغيل المفاجئ للعدة الكهربائية وقوع حوادث بالتأكيد.

2 قوة ضغط المتنبّع

لا يمكنك الحصول على التقوّب بسرعة حتى عند الضغط عليها بواسطة القوة المفرطة أكثر من اللازم. فلا يؤدي ذلك إلى تلتف ظرف المتنبّع الحفر وتقليل كفاءة التشغيل فقط بل يؤدي أيضاً إلى تقصير عمر المتنبّع.


3 عند التقبّب داخل المادة بالكامل


عندما يختفي المتنبّع تماماً عبر المادة، قد يؤدي التعامل بإهمال غالباً إلى كسر المتنبّع أو لف هيكل المتنبّع ذاته بسبب الحركة المفاجئة للمنتسب. كن بـقطاً ومستعداً لتمرير قوة الدفع وأحكام جسم المتنبّع بأمان بكلتا اليدين عند التقبّب عبر المادة.


Item No.	Part Name	Item No.	Part Name
1	Tapping Screw D5 × 40	34	Contoroller Circuit
2	Gear Cover	35	Cord Clip
3	Ball Bearing (6001VV/CMPS2L)	36	Tapping Screw (W/Flange) D4 × 16
4	Second Pinion	37	Tapping Screw (W/Flange) D4 × 20
5	First Gear	38	Terminal
6	Ball Bearing (606ZZC2PS2L)	39	Cord Armor
7	Bearing Lock	40	Tail Cover
8	Inner Cover	41	Tapping Screw (W/Flange) D4 × 16
9	Ball Bearing (608DDC2PS2L)	42	Cord
10	Armature	43	BRAND Label
11	Fan Guide	44	Slide Knob
12	Hex. Hd. Tapping Screw D4 × 70	45	Slide Bar
13	Stator Assy	46	Switch
14	Terminal	47	Spring
15	Dust Seal	48	Reversing Switch
16	Ball Bearing (626VVC2PS2L)	49	Connector (50091)
17	Flat Fillerter Hd. Screw M4 × 10	50	Pillar Terminal
18	Ball Bearing (607VV/C2PS2L)	501	Side Handle
19	Spindle		
20	Gear		
21	Chuck Cover		
22	Seal Lock Hex. Socket Hd. Bolt M3 × 12		
23	Felt Packing (A)		
24	Felt Packing		
25	Drill Chuck 10TLRD		
26	Chuck Wrench		
27	Flat Hd. Screw (Left Hand) M5 × 15		
28	Brush Holder		
29	Carbon Brush		
30	Brush Cap		
31	Rubber Bushing		
32	Housing Ass'y		
33	Name Plate		

Parts are subject to change without any obligation on the part of the HikOKI due to improvements.

The exploded assembly drawing should be used only for authorized service center.







Koki Holdings Co.,Ltd.

806

Code No. C99101534 N
Printed in Japan